



## Global MX-5 Cup Car Technical Service Bulletin #05-23-2017

### Optional: 2017 Global MX-5 Update: Front Sway bar mounting hardware

#### This TSB describes:

1. The front sway bar mounting bracket may become stressed or fatigued, you have the option of using a larger diameter washer (see picture below).

#### Installation:

1. Remove and replace front sway bar nut and washer, replace with a larger diameter washer. Use thread sealant and torque the nut to 15 – 18 foot pounds



If you have any questions about this Technical Bulletin, please contact Flis Performance at: [Ashli@FlisPerformance.com](mailto:Ashli@FlisPerformance.com) or 386-256-7021