



## Global MX-5 Cup Car Technical Service Bulletin #05-23-2018B

### Optional: Global MX-5 Update: Starter power lead

#### This TSB describes:

1. The main 12V power lead for the starter should be checked for chafing to ground.

#### Installation:

1. Verify and correct with insulation, and or, re-clocking the starter hot wire (red arrow below) that the starter wire does not contact the chassis bracket (green arrow).



If you have any questions about this Technical Bulletin, please contact Flis Performance at:  
Ashli@FlisPerformance.com or 386-256-7021