



Global MX-5 Cup Car Technical Service Bulletin #07-27-2019

Optional: Global MX-5 Cup Radiator Cap Safety wire hole(s)

This TSB describes: The purpose of this TSB is to allow competitors to drill a hole in each ear(s) of either homologated radiator cap per the picture below. The competitor may then safety-wire the cap if desired. No other modifications to the radiator cap or use of the safety wire is permitted.

This TSB takes effect on July 27, 2019



If you have any questions about this Technical Bulletin, please contact Flis Performance at: ashli@flisperformance.com or 386-256-7021