



Global MX-5 Cup Car Technical Service Bulletin #03-13-2020

Required: Global MX-5 Cup ND2, Bosch MS6 Cup ECU Update, Release 0106c

This TSB describes:

An Update is available for the Bosch MS6 Cup ECU for the Global MX-5 Cup ND.2. This update includes the following:

- Voltage Control Update

Note that the AiM Configuration was last updated in December to Version 01.28.20 and will need to be updated if not done so already. Always update the RaceStudio3 software prior to updating configuration files to ensure the latest ECU drivers are being used. The latest RaceStudio3 software can be downloaded at the [AiM website](#).

The update will show as Software ID “MS6A_MX5CUP_0105” and the Software version will show as “MX50019”.

The screenshot shows the RaceStudio3 software interface. At the top, there are tabs for 'Connection', 'Mode', 'Measuring', and 'Data'. Below these, there is a section for 'Engine Measurement' with a sub-section for 'Software ID'. This section contains a table with the following data:

CAR ID	LRR_MX5
SOFTWARE ID	MS6A_MX5CUP_0105_g..
ECU Serial Num.	1601

Below the 'Software ID' section, there is a 'Software Version' section with a table:

v	M
e	X
r	5
s	0
i	0
o	1
n	9

To the right of the 'Software Version' table, there is a large green gear icon with a stylized 'FP' inside it, which is the Flis Performance logo.

The Update Instructions and all supporting files can be found on the ND.2 Documentation page of the Flis Performance website.

Global MX-5 Cup ND.2 ECU Update Instructions 3-10-20 - [LINK](#)

TEAM License file: [MazdaMX_2020_TEAM.lic](#) - [LINK](#)

TEAM Project file: [MX5 Cup_0106b_Release_TEAM_03_10_2020](#)- [LINK](#)

Firmware file: [MS6A_MX5CUP_0106c.psv](#)- [LINK](#)

RaceCon Overview: [MX5 RaceCon Overview](#) - [TEAM FP](#)- [LINK](#)

If you have any questions about this Technical Bulletin, please contact Flis Performance at: ashli@flisperformance.com or 386-256-7021