



Global MX-5 Cup Car Technical Service Bulletin #05-23-2018C.1

Optional: Global MX-5 Update: Fascia reinforcements

This TSB describes:

To reduce fascia damage from incidental corner contact and reduce the need for front fender liners, this TSB allows for adding corner braces inside to the front and rear fascia's corners. These parts are available only from Mazda Competition parts. The part numbers are....

Front fender liners are now optional, with the installation of this TSB only. The fascia braces will now replace the locating properties of the front fender liners. Please keep in mind, that if you choose to not run the front fender liners, dirt, water and debris have direct access to the main wiring loom and the engine compartment. It is highly recommended to keep the front fender liners in place.

The part numbers for the individual components are listed below. All 7 part numbers must be ordered for the initial installation for a car.

Description	P/N
Fascia Support Right Front	0000-07-5810-RF
Fascia Support Left Front	0000-07-5811-LF
Fascia Support Right Rear	0000-07-5812-RR
Fascia Support Left Rear	0000-07-5813-LR
Fascia Support Frame Clip Right Rear	0000-07-5814-RR
Fascia Support Frame Clip Left Rear	0000-07-5815-LR
Rear Fascia Support Weld Bung Kit	0000-07-5816

Installation:

Detailed instructions will be provided with the parts.

NOTE: The installation of the Fascia Supports will require the welding of 4 threaded bungs on both of the rear corners. These bungs go into existing holes in the frame rails, no drilling, just welding. The fascia supports install in place of the existing plastic supports in the rear, and install using the factory fog light mounts in the front bumper cover and threaded bungs and studs that already exist on the front sub frame.

If you have any questions about this Technical Bulletin, please contact Flis Performance at: Ashli@FlisPerformance.com or 386-256-7021