



## Mazda MX-5 Cup Competitor Information Bulletin #2024-11-04

This CIB describes: Differential Repair and Refurbishing Procedures

Please be advised of an important service requirement for all Mazda MX-5 Cup competitors regarding differential repairs and refurbishing. To maintain optimal performance, reliability, and compliance with series regulations, differentials requiring service must be sent to the contact listed below at Detroit Speed. This is the only authorized location for Mazda MX-5 Cup Cars to receive service without voiding the seals.

### Contact for Differential Services:

Detroit Speed  
Matthew Bellamy  
Sales Manager  
Phone: 980-920-5706  
Email: [mattbellamy@holley.com](mailto:mattbellamy@holley.com)  
Address: 185 McKenzie Rd  
 Mooresville, NC 28115

Please reach out to Matthew directly with any questions or to arrange for service. Ensuring your differential is serviced at Detroit Speed will adhere to compliance and maintain the integrity of your vehicle's performance.

Should you have any further questions or require additional information, please do not hesitate to contact us.

Ashli Richardson

☎ 386-256-7021

✉ [ASHLI@FLISPERFORMANCE.COM](mailto:ASHLI@FLISPERFORMANCE.COM)

🌐 [WWW.FLISPERFORMANCE.COM](http://WWW.FLISPERFORMANCE.COM)

📍 106 ANITA AVE  
DAYTONA BEACH, FL  
32114



WHELEN  
MAZDA  
MX-5 CUP

PRESENTED BY MICHELIN

MAZDA  
MOTORSPORTS

HERITAGE COLLECTION